

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2016

Submitted Date:

11/10/2016

Document Number:

674103823**FIELD INSPECTION FORM**

Loc ID 431232 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name       | Phone | Email                                  | Comment |
|--------------------|-------|--|---------|
| Inspections, Noble |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 431234      | WELL | PR     | 07/10/2013  | OW         | 123-36496 | SLW RANCH STATE B13-69HN   | PR          |
| 431241      | WELL | PR     | 07/10/2013  | OW         | 123-36502 | SLW RANCH STATE B12-63-1HN | PR          |
| 431247      | WELL | PR     | 10/25/2013  | OW         | 123-36505 | SLW Ranch B12-79HN         | PR          |
| 431259      | WELL | PR     | 07/05/2013  | OW         | 123-36512 | SLW RANCH STATE B12-64-1HN | PR          |
| 431282      | WELL | PR     | 07/09/2013  | OW         | 123-36532 | SLW RANCH STATE B12-62-1HN | PR          |

**General Comment:**

| Inspected Facilities                        |            |                       |            |                  |
|---|------------|-----------------------|------------|------------------|
| Facility ID: 431234                         | Type: WELL | API Number: 123-36496 | Status: PR | Insp. Status: PR |
| <b><u>Producing Well</u></b>                |            |                       |            |                  |
| Comment: PR                                 |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| <b><u>BradenHead</u></b>                    |            |                       |            |                  |
| Comment: Braden head is exposed at surface. |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| Facility ID: 431241                         | Type: WELL | API Number: 123-36502 | Status: PR | Insp. Status: PR |
| <b><u>Producing Well</u></b>                |            |                       |            |                  |
| Comment: PR                                 |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| <b><u>BradenHead</u></b>                    |            |                       |            |                  |
| Comment: Braden head is exposed at surface. |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| Facility ID: 431247                         | Type: WELL | API Number: 123-36505 | Status: PR | Insp. Status: PR |
| <b><u>Producing Well</u></b>                |            |                       |            |                  |
| Comment: PR                                 |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| <b><u>BradenHead</u></b>                    |            |                       |            |                  |
| Comment: Braden head is exposed at surface. |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| Facility ID: 431259                         | Type: WELL | API Number: 123-36512 | Status: PR | Insp. Status: PR |
| <b><u>Producing Well</u></b>                |            |                       |            |                  |
| Comment: PR                                 |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| <b><u>BradenHead</u></b>                    |            |                       |            |                  |
| Comment: Braden head is exposed at surface. |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |
| Facility ID: 431282                         | Type: WELL | API Number: 123-36532 | Status: PR | Insp. Status: PR |
| <b><u>Producing Well</u></b>                |            |                       |            |                  |
| Comment: PR                                 |            |                       |            |                  |
| Corrective Action:                          |            | Date:                 |            |                  |

**BradenHead**

Comment:

Corrective Action:

Date:

| Environmental                      |  |
|------------------------------------|--|
| <b>Spill/Remediation:</b>          |  |
| Comment:                           |  |
| Corrective Action:                 | Date:  |
| Emission Control Burner (ECB): YES |  |
| Comment:                           |  |
| Pilot:                             | Wildlife Protection Devices (fired vessels): YES |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IRRIGATED

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| Location inventory has not changed since last inspection. | rickardj | 11/10/2016 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 674103823    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005096">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005096</a> |