

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/10/2016

Submitted Date:

11/10/2016

Document Number:

675203600**FIELD INSPECTION FORM**
 Loc ID 438312 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	All Inspections
Bleil, Rob	(970) 329-4373	rbleil@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438303	WELL	WO	09/16/2016	LO	045-22475	TOMPKINS 32B-08-07-95	PR
438305	WELL	WO	09/16/2016	LO	045-22477	TOMPKINS 32A-08-07-95	PR
438306	WELL	WO	09/16/2016	LO	045-22478	TOMPKINS 42A-08-07-95	PR
438310	WELL	DG	08/16/2016	LO	045-22482	TOMPKINS 41B-08-07-95	PR
438313	WELL	WO	09/16/2016	LO	045-22484	TOMPKINS 31B-08-07-95	PR
441197	WELL	WO	09/16/2016	LO	045-22822	TOMPKINS 21C-08-07-95	PR

General Comment:[Flowback inspection. Water is being stored on location for stimulation. No evidence of leaks or spills at time of inspection.](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER			STEEL AST		,	
Comment: Tanks for storage of flowback/Stimulation water.						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	600bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 438303 Type: WELL API Number: 045-22475 Status: WO Insp. Status: PRFacility ID: 438305 Type: WELL API Number: 045-22477 Status: WO Insp. Status: PR**Workover**Comment: FLOWBACKCorrective Action: Date: Facility ID: 438306 Type: WELL API Number: 045-22478 Status: WO Insp. Status: PR**Workover**Comment: FLOWBACKCorrective Action: Date: Facility ID: 438310 Type: WELL API Number: 045-22482 Status: DG Insp. Status: PR**Workover**Comment: FLOWBACKCorrective Action: Date: Facility ID: 438313 Type: WELL API Number: 045-22484 Status: WO Insp. Status: PR**Workover**Comment: FLOWBACKCorrective Action: Date: Facility ID: 441197 Type: WELL API Number: 045-22822 Status: WO Insp. Status: PR**Workover**Comment: FLOWBACKCorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203600	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006415