



**photo 1:** Facing west along the access road.



**photo 2:** East side of the location facing southwest.





**photo 3:** Southeast side of the location facing southwest



**photo 4:** South side of the location facing northeast.





**photo 5:** South side of the location facing northwest.



**photo 6:** There is a patch of noxious weeds (Common mullein) at the northwest side of the location.





**photo 7:** Rock rip/rap has been placed at the north side of the location.



**photo 8:** North side of the location facing south.





**photo 9:** North side of the location facing southeast along the fill slope.



**photo 10:** Facing northwest along the fill slope.