

Stormwater Inspection



Photo 1. Photo taken from the western location, facing North. Installed wattles along the potential discharge point.

Stormwater Inspection



Photo 2. Photo taken from the approximate center of the location, facing North. Additional spills were observed outside of this photo, throughout the location. Control and contain spills/releases and clean up per Rule 906.a.

Stormwater Inspection



Photo 3. Photo taken from the approximate center of the location, facing Northwest. Additional spills were observed outside of this photo, throughout the location. Control and contain spills/releases and clean up per Rule 906.a.