

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/15/2016  
Submitted Date:  
11/15/2016  
Document Number:  
674103841

**FIELD INSPECTION FORM**

Loc ID 433811 Inspector Name: Rickard, Jeff On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433810	WELL	PR	12/02/2014	OW	123-37792	Boyd 3E-19H-M368	PR
433812	WELL	PR	12/02/2014	OW	123-37793	Boyd 3B-19H-M368	PR
433813	WELL	PR	12/02/2014	OW	123-37794	Boyd 3G-19H-M368	PR
433814	WELL	PR	12/02/2014	OW	123-37795	Boyd 3C-19H-M368	PR
433815	WELL	PR	05/05/2015	OW	123-37796	Boyd 3D-19H-M368	PR
433816	WELL	PR	12/02/2014	OW	123-37797	Boyd 3F-19H-M368	PR

**General Comment:**

Inspected Facilities			
Facility ID: 433810	Type: WELL	API Number: 123-37792	Status: PR
<b>Producing Well</b>			
Comment: PR	Corrective Action:		Date:
<b>Complaint</b>			
Comment: Complaint DOC# 200440545. Area resident complained about noise coming from the Crestone location at HWY 66 and County Line Road. OGCC staff was on location on 11/15/16. There was a VRU running on location behind sound walls. A sound survey was run 350 ft from the VRU (the noise source) to the SW of location which was in the direction of the complainant. The sound survey resulted in a LeqA of 47.3db. The A scale noise was evaluated due to traffic on HWY 66, however the 47.3db is in compliance with Rule 803 for battery operations day and night 18A DOC#20440548.	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: Braden head is exposed at surface.	Corrective Action:		Date: _____
Facility ID: 433812	Type: WELL	API Number: 123-37793	Status: PR
<b>Producing Well</b>			
Comment: PR	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: Braden head is exposed at surface.	Corrective Action:		Date: _____
Facility ID: 433813	Type: WELL	API Number: 123-37794	Status: PR
<b>Producing Well</b>			
Comment: PR	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: Braden head is exposed at surface.	Corrective Action:		Date: _____
Facility ID: 433814	Type: WELL	API Number: 123-37795	Status: PR
<b>Producing Well</b>			
Comment: PR	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: Braden head is exposed at surface.	Corrective Action:		Date: _____

Facility ID: 433815    Type: WELL    API Number: 123-37796    Status: PR    Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 433816    Type: WELL    API Number: 123-37797    Status: PR    Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103841	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008562">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008562</a>
674103842	Sound survey	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003604</a>