

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2016

Submitted Date:

11/22/2016

Document Number:

679700290**FIELD INSPECTION FORM**
 Loc ID 317501 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10017Name of Operator: CHACO ENERGY COMPANYAddress: P O BOX 1587City: DENVER State: CO Zip: 80201**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Alan Nelson		chaco@swbell.net	
Kurt Nelson		kurt@chacoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117928	PIT	AC			-	ROTHROCK 1	EI
238571	WELL	PR	01/01/2015	GW	123-05432	KERITH ROTHROCK 1	EI

General Comment:

COGCC Environmental Staff followup inspection for skim pit closure at Rothrock #1 location. Corrective actions from Inspections 684900209 and 684900237 have also been completed.

Inspected Facilities									
Facility ID:	117928	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	238571	Type:	WELL	API Number:	123-05432	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 117928Lat: 40.604152Long: -103.733650Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment:

Skim pit/tinhorn has been removed. No oily waste is present on the location. Skim pit was replaced with a buried fiberglass skim tank. Well is producing, water flowing to two remaining produced water pits on the location. Remediation Project #9888 will be resolved upon receipt of final laboratory analysis and waste disposal documentation.

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700291	Skim pit excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008921
679700292	New skim tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008922
679700293	Produced water pit #1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008923
679700294	Produced water pit #2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008924