

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/21/2016  
Submitted Date:  
11/22/2016  
Document Number:  
679700321

**FIELD INSPECTION FORM**

Loc ID 327976 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10311  
Name of Operator: SYNERGY RESOURCES CORPORATION  
Address: 20203 HIGHWAY 60  
City: PLATTEVILLE State: CO Zip: 80651

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Pennington, David		dpennington@syrginfo.com	<a href="#">All Synergy Inspections</a>
Jerry Brian		jbrian@syrginfo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113418	PIT	AC			-	TOEDTLI	EI

**General Comment:**

[COGCC Environmental Staff followup to inspection 684901247 and Pit Inspection at Toedtli 1-10. Corrective Actions listed on Inspection 684901247 have been completed.](#)

**Inspected Facilities**

Facility ID: 113418 Type: PIT API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 113418 Lat: 40.851038 Long: -103.739836

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: Metal Grid Netting Condition: Good

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Two pits are present on location. Operator has cleaned up oily waste from former skim pit and renetted the pit. Operator plans to maintain former skim pit as a produced water pit. Operator plans to close larger, non-netted produced water pit.

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700322	Former skim pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009101">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009101</a>
679700323	Larger produced water pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009102">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009102</a>