

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2016

Submitted Date:

11/16/2016

Document Number:

675203615**FIELD INSPECTION FORM**
 Loc ID 322449 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:                     
**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Allred, Josh	(970) 629-5914	jallred@foundationenergy.com	Field Supervisor
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Contact, General		regulatory@foundationenergy.com	Regulatory

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210531	WELL	PR	07/09/2014	GW	045-06287	FEDERAL 1-3-8-104	PR

**General Comment:**

Follow up to inspection Doc#675203163 and 675203384. Corrective actions have not been met from previous inspections.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Vegetation around equipment and in pit. CA has not been met. See attached photos.

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 09/10/2016

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

<b>Inspected Facilities</b>			
Facility ID: <u>210531</u>	Type: <u>WELL</u>	API Number: <u>045-06287</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: Areas of road show signs of erosion.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: EvaporationLined: NOPit ID: 119457Lat: 39.400152Long: -108.971380

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: c**Fencing:**Fencing Type: Netting/Fence comFencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**Netting Type: Fence/Net ComboNetting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment: See housekeeping section of inspection.

Corrective Action

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203615	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004253">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004253</a>
675203616	Inspection 11-15-16	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004212</a>
675203617	INspection 10-6-16	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004213</a>