

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/21/2016

Submitted Date:

11/22/2016

Document Number:

679700321**FIELD INSPECTION FORM**
 Loc ID 327976 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Jerry Brian		jbrian@syrginfo.com	
Pennington, David		dpennington@syrginfo.com	All Synergy Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113418	PIT	AC			-	TOEDTLI	EI

General Comment:

[COGCC Environmental Staff followup to inspection 684901247 and Pit Inspection at ToedtlI 1-10. Corrective Actions listed on Inspection 684901247 have been completed.](#)

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 113418Lat: 40.851038Long: -103.739836Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Metal GridNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment:

Two pits are present on location. Operator has cleaned up oily waste from former skim pit and renetted the pit. Operator plans to maintain former skim pit as a produced water pit. Operator plans to close larger, non-netted produced water pit.

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700321	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009135
679700322	Former skim pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009101
679700323	Larger produced water pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009102