



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Vegetation within the interim reclamation area is sparse and patchy.





Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of the western portion of the project area from the southwestern corner facing northward.





Photo 5. View of stormwater controls along the southern edge of the well pad and access road that appear to be functioning.



Photo 6. View of the beginning of Transect 1-within the interim reclamation area facing southward.





Photo 7. Birdseye view of vegetation at the midpoint along Transect 1.





Photo 8. View of Transect 2- within the reference area, outside of the project area facing northward.





Photo 9. Birdseye view of vegetation at the midpoint of Transect 2.