

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/15/2016
Submitted Date:
11/25/2016
Document Number:
680101295

FIELD INSPECTION FORM

Loc ID 335617 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10516
Name of Operator: LINN OPERATING INC
Address: 600 TRAVIS STREET #5100
City: HOUSTON State: TX Zip: 77002

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|--------------------|
| | | thogelin@linnenergy.com | |
| | | bburns@linnenergy.com | |
| White, B | | bwhite@linnenergy.com | Production Foreman |
| | | dsjohnson@linnenergy.com | |
| | | MFoster@linnenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 287081 | WELL | XX | 10/02/2013 | LO | 045-12886 | GRANLEE OM 08D I02 696 | RI |
| 287082 | WELL | XX | 10/02/2013 | LO | 045-12885 | GRANLEE 09A I02 696 | RI |
| 287083 | WELL | XX | 10/02/2013 | LO | 045-12884 | GRANLEE OM09B I02 696 | RI |
| 287084 | WELL | PR | 05/09/2008 | GW | 045-12883 | GRANLEE OM 9C I02 696 | RI |
| 287085 | WELL | PR | 01/29/2008 | GW | 045-12882 | GRANLEE OM 09D I02 696 | RI |
| 287086 | WELL | PR | 01/29/2008 | GW | 045-12881 | GRANLEE OM 16A I02 696 | RI |
| 287087 | WELL | PR | 02/05/2008 | GW | 045-12880 | GRANLEE OM 10D I02 696 | RI |

General Comment:

This is an Interim Reclamation and Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. Operator has Submitted "Status Of Pre Set Conductors" of which there are Three on Location. there is a small site of Land Farming at NE corner of Pad just into the Interim Reclamation Area.

Inspected Facilities

Facility ID: 287081 Type: WELL API Number: 045-12886 Status: XX Insp. Status: RI

Facility ID: 287082 Type: WELL API Number: 045-12885 Status: XX Insp. Status: RI

Facility ID: 287083 Type: WELL API Number: 045-12884 Status: XX Insp. Status: RI

Facility ID: 287084 Type: WELL API Number: 045-12883 Status: PR Insp. Status: RI

Facility ID: 287085 Type: WELL API Number: 045-12882 Status: PR Insp. Status: RI

Facility ID: 287086 Type: WELL API Number: 045-12881 Status: PR Insp. Status: RI

Facility ID: 287087 Type: WELL API Number: 045-12880 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Range Land

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? Pass
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment Interim Reclamation is fenced, three strand wire. Gate is open at North Corner of Pad into Reclamation. Fence has been Cut at NE corner, it appears as access to small Land Farming site. It is recommended to install Gate at this point and keep all gates shut to exclude Livestock from Reclamation as it is establishing. Interim Reclamation had large population of Annual Weeds in past Growing season; but grasses are establishing. Refer to Photos attached

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

| | | | | | | |
|---|--|-------------------------|-----------------------|---------------|--------------------------|-------------|
| Corrective Action: _____ | Date _____ | | | | | |
| Overall Final Reclamation _____ | Well Release on Active Location <input type="checkbox"/> | | | | | |
| | Multi-Well Location <input type="checkbox"/> | | | | | |
| Storm Water: | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |
| Comment: Site is Stable and has no soil Migration issues. | | | | | | Date: _____ |
| Corrective Action: _____ | | | | | | Date: _____ |
| Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

| COGCC Comments | | |
|--|--------|------------|
| Comment | User | Date |
| Gate is open at North Corner of Pad into Reclamation. Fence has been Cut at NE corner, it appears as access to small Land Farming site. It is recommended to install Gate at this point and keep all gates shut to exclude Livestock from Reclamation as it is establishing. Refer to Photos attached. | colbyl | 11/25/2016 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 680101295 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017129 |
| 680101296 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4011804 |