



Photo#1: View to North over Location at Fence Corner where Fence was Cut.

November 16, 2016

Inspection Photos: OXY USA WPT Cascade Creek PA 045-06870



Photo#2: View South over Location

November 16, 2016

Inspection Photos: OXY USA WPT Cascade Creek PA 045-06870





Photo#3: Gate at North end is Intact.

November 16, 2016

Inspection Photos: OXY USA WPT Cascade Creek PA 045-06870





Photo#4: Noxious weeds on Location.

November 16, 2016

Inspection Photos: OXY USA WPT Cascade Creek PA 045-06870





Photo#5: Vegetation has been severely Grazed.