

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/21/2016

Submitted Date:

11/29/2016

Document Number:

666802751

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
323932 _____ Murray, Richard _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------|------------------------|
| Ghan, Scott | | sghan@vnrlc.com | Sr. EH&S |
| Axelson, Aaron | 970-230-0926 | aaxelson@vnrlc.com | Sr. Production Foreman |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 211290 | WELL | PR | 05/25/1996 | GW | 045-07049 | LEGG 2-26-6-92 | PR |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment: Landowner has stored equipment and debris on location

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---|---|-----------|-----------|---------|----------------------------|
| CONDENSATE | 1 | <100 BBLS | PBV STEEL | | , |
| Comment: Centralized battery | | | | | |
| Corrective Action: <input type="text"/> | | | | | Date: <input type="text"/> |

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: <input type="text"/> | | | | |

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | 39.503807,-107.633039 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|-----------------------|-------|--|
| Yes/No | YES | | |
| Comment: | Bradenhead valve open | | |
| Corrective Action: | | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 211290 Type: WELL API Number: 045-07049 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |
| Seeding | Pass | | | | | |
| | | Gravel | Pass | | | |
| | | Ditches | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 666802751 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019124 |