


Final Reclamation Inspection- Overview



Google Earth aerial photo taken 9/7/2016 illustrating total extent of disturbance. Well location passes Rule 1004 standards. Tank battery location IN-PROCESS. Appears that approximately 400' of the access road has not been reclaimed.

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 5. Reference photo taken east of location, facing East. Location appears to be reflective of the reference areas.

Final Reclamation Inspection



Photo 6. Photo taken from the tank battery location (i.e., fenced in location), facing Northwest. Location IN-PROCESS. A seeding attempt is evident but location lacks uniform vegetative growth that is not reflective of reference areas.