

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2016

Submitted Date:

12/08/2016

Document Number:

685301938**FIELD INSPECTION FORM**

Loc ID 325616	Inspector Name: St John, William (Cal)	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10000</u> Name of Operator: <u>BP AMERICA PRODUCTION COMPANY</u> Address: <u>380 AIRPORT RD</u> City: <u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Brown, Walt	970-385-1372	wabrown@fs.fed.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215110	WELL	PR	06/30/1986	GW	067-06715	FEDERAL 02L-01 #1	PR

General Comment:

Inspection report is in response to request to adjust completion due date for open Storm Water corrective action identified in Inspection Report document number 685301722. Well is located in the San Juan National Forest which has a winter closure period from December 1 until April 30 to protect wintering big game species. Due to closure period it has been requested the the repairs be delayed until after the closure period is over. The area is already seeing usage by wildlife and Forest Service would prefer that the work be completed after May 1, 2017. See Storm Water Section of this report for additional details. See link at end of report for path to downloadable picture from document 685301722.

Inspected Facilities									
Facility ID:	<u>215110</u>	Type:	<u>WELL</u>	API Number:	<u>067-06715</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					
Berms	Pass	Compaction	Pass			
Ditches	Pass					

Comment: Erosion channel on SW corner of fill slope. Additional comments - In the interim i have requested that operator attempt to stabilize the area to prevent further erosion until the winter closure period is over.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for additional details.

Date: 05/31/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301939	Erosion channels on SW corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022471