

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2016

Submitted Date:

12/02/2016

Document Number:

682401580**FIELD INSPECTION FORM**

Loc ID 447778	Inspector Name: Binschus, Chris	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED								
Operator Information: OGCC Operator Number: <u>10261</u> Name of Operator: <u>BAYSWATER EXPLORATION AND PRODUCTION LLC</u> Address: <u>730 17TH ST STE 610</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>			Findings: 8 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested								
Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Blyth, Tom</td> <td>(303) 893-2503</td> <td>tblyth@bayswater.us</td> <td>All inspections</td> </tr> </table>				Contact Name	Phone	Email	Comment	Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	All inspections
Contact Name	Phone	Email	Comment								
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	All inspections								

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447777	WELL	DG	11/03/2016		123-43589	Thornton H-29-30HC	CI
447779	WELL	XX	09/16/2016		123-43590	Thornton O-29-30HN	CI
447780	WELL	XX	09/16/2016		123-43591	Thornton Q-29-30HC	CI
447781	WELL	DG	10/31/2016		123-43592	Thornton L-29-30HN	CI
447782	WELL	XX	09/16/2016		123-43593	Thornton F-29-30HN	CI
447783	WELL	XX	09/16/2016		123-43594	Thornton W-29-30HC	CI
447784	WELL	XX	09/16/2016		123-43595	Thornton M-29-30HN	CI
447785	WELL	DG	11/02/2016		123-43596	Thornton J-29-30HN	CI
447786	WELL	XX	09/16/2016		123-43597	Thornton E-29-30HC	CI
447787	WELL	DG	11/04/2016		123-43598	Thornton G-29-30HN	CI
447788	WELL	DG	11/01/2016		123-43599	Thornton K-29-30HC	CI
447789	WELL	XX	09/16/2016		123-43600	Thornton P-29-30HN	CI
447790	WELL	XX	09/16/2016		123-43601	Thornton U-29-30HN	CI
447791	WELL	XX	09/16/2016		123-43602	Thornton N-29-30HC	CI
447792	WELL	XX	09/16/2016		123-43603	Thornton V-29-30HN	CI
447793	WELL	XX	09/16/2016		123-43604	Thornton D-29-30HN	CI
447794	WELL	XX	09/16/2016		123-43605	Thornton A-29-30HN	CI
447795	WELL	XX	09/16/2016		123-43606	Thornton S-29-30HN	CI
447796	WELL	XX	09/16/2016		123-43607	Thornton R-29-30HN	CI
447797	WELL	XX	09/16/2016		123-43608	Thornton X-29-30HN	CI
447798	WELL	DG	11/02/2016		123-43609	Thornton I-29-30HN	CI
447799	WELL	XX	09/16/2016		123-43610	Thornton C-29-30HN	CI
447800	WELL	XX	09/16/2016		123-43611	Thornton B-29-30HC	CI
447801	WELL	XX	09/16/2016		123-43612	Thornton T-29-30HC	CI

General Comment:
[This is a construction and stormwater inspection in response to Form 42 Document #401120994- Notice of construction of a new location.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location ConstructionLocation ID: CDP:

Comment:

Corrective Action: Date: **Form 2A COAs:**Comment: Corrective Action: Date: **Wildlife BMPs:**Comment: Corrective Action: Date: **Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
SILT FENCES	Yes		
Comments: Erosion BMPs:	<input type="text"/>		
Other BMPs:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

RETENTION PONDS	Yes		
Comments: Erosion BMPs: 3 potential retention ponds have been installed. The retention pond at the location entrance has not been completed. Rig on location. Final BMPs should be completed.			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action:		Date:	
BERMS	Yes		
Comments: Erosion BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action:		Date:	
WADDLES	Yes		
Comments: Erosion BMPs: Wattles have been installed throughout the location; however, wattles have not been trenched and backfilled to prevent undermining. May need to monitor to ensure BMP properly functions.			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action:		Date:	
DITCHES	Yes		
Comments: Erosion BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action:		Date:	

Comment: Refer to attached photo in Document #682401581.

Corrective Action:**Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>447777</u>	Type: <u>WELL</u>	API Number: <u>123-43589</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447779</u>	Type: <u>WELL</u>	API Number: <u>123-43590</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447780</u>	Type: <u>WELL</u>	API Number: <u>123-43591</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447781</u>	Type: <u>WELL</u>	API Number: <u>123-43592</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447782</u>	Type: <u>WELL</u>	API Number: <u>123-43593</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447783</u>	Type: <u>WELL</u>	API Number: <u>123-43594</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447784</u>	Type: <u>WELL</u>	API Number: <u>123-43595</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447785</u>	Type: <u>WELL</u>	API Number: <u>123-43596</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447786</u>	Type: <u>WELL</u>	API Number: <u>123-43597</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447787</u>	Type: <u>WELL</u>	API Number: <u>123-43598</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447788</u>	Type: <u>WELL</u>	API Number: <u>123-43599</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447789</u>	Type: <u>WELL</u>	API Number: <u>123-43600</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447790</u>	Type: <u>WELL</u>	API Number: <u>123-43601</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447791</u>	Type: <u>WELL</u>	API Number: <u>123-43602</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447792</u>	Type: <u>WELL</u>	API Number: <u>123-43603</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447793</u>	Type: <u>WELL</u>	API Number: <u>123-43604</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447794</u>	Type: <u>WELL</u>	API Number: <u>123-43605</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447795</u>	Type: <u>WELL</u>	API Number: <u>123-43606</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447796</u>	Type: <u>WELL</u>	API Number: <u>123-43607</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Facility ID: 447797	Type: WELL	API Number: 123-43608	Status: XX	Insp. Status: CI
Facility ID: 447798	Type: WELL	API Number: 123-43609	Status: DG	Insp. Status: CI
Facility ID: 447799	Type: WELL	API Number: 123-43610	Status: XX	Insp. Status: CI
Facility ID: 447800	Type: WELL	API Number: 123-43611	Status: XX	Insp. Status: CI
Facility ID: 447801	Type: WELL	API Number: 123-43612	Status: XX	Insp. Status: CI

COGCC Comments

Comment	User	Date
Follow up inspection might proceed to ensure completion of BMPs. Other stormwater and erosion control BMPs have already been installed, and the location appears to be stabilized along the fill slopes and cut slopes.	binschusc	12/02/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401580	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022998
682401581	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017784