

Iles Dome Unit 37

Inspection# 673403915

Active leak at wellhead.

12/6/2016



Active leak at wellhead.

12/6/2016



Leak and stained soil at wellhead.

9/6/2016



Leak and stained soil at wellhead.

9/6/2016

