

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2016

Submitted Date:

12/08/2016

Document Number:

685301938**FIELD INSPECTION FORM**
 Loc ID 325616 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Walt	970-385-1372	wabrown@fs.fed.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215110	WELL	PR	06/30/1986	GW	067-06715	FEDERAL 02L-01 #1	PR

**General Comment:**

Inspection report is in response to request to adjust completion due date for open Storm Water corrective action identified in Inspection Report document number 685301722. Well is located in the San Juan National Forest which has a winter closure period from December 1 until April 30 to protect wintering big game species. Due to closure period it has been requested the the repairs be delayed until after the closure period is over. The area is already seeing usage by wildlife and Forest Service would prefer that the work be completed after May 1, 2017. See Storm Water Section of this report for additional details. See link at end of report for path to downloadable picture from document 685301722.

Inspected Facilities									
Facility ID:	215110	Type:	WELL	API Number:	067-06715	Status:	PR	Insp. Status:	PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					
Berms	Pass	Compaction	Pass			
Ditches	Pass					

Comment: Erosion channel on SW corner of fill slope. Additional comments - In the interim i have requested that operator attempt to stabilize the area to prevent further erosion until the winter closure period is over.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for additional details.

Date: 05/31/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301938	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027957">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027957</a>
685301939	Erosion channels on SW corner	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022471">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022471</a>