

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/09/2016  
Submitted Date:  
12/09/2016  
Document Number:  
674004696

**FIELD INSPECTION FORM**

Loc ID 330721 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440242	WELL	DG	10/26/2015	LO	123-40753	Moser H34-725	DG
440243	WELL	DG	11/20/2015	LO	123-40754	Moser H22-715	DG
440244	WELL	DG	11/12/2015	LO	123-40755	Moser H34-717	DG
440245	WELL	DG	11/03/2015	LO	123-40756	Moser H22-725	DG
440246	WELL	DG	11/27/2015	LO	123-40757	Moser H22-711	DG

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	440242	Type:	WELL	API Number:	123-40753	Status:	DG	Insp. Status:	DG
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
<b>BradenHead</b>									
Comment:	Bradenhead plubed to surface.								
Corrective Action:					Date:				
Facility ID:	440243	Type:	WELL	API Number:	123-40754	Status:	DG	Insp. Status:	DG
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
<b>BradenHead</b>									
Comment:	Bradenhead plubed to surface.								
Corrective Action:					Date:				
Facility ID:	440244	Type:	WELL	API Number:	123-40755	Status:	DG	Insp. Status:	DG
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
<b>BradenHead</b>									
Comment:	Bradenhead plubed to surface.								
Corrective Action:					Date:				
Facility ID:	440245	Type:	WELL	API Number:	123-40756	Status:	DG	Insp. Status:	DG
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
<b>BradenHead</b>									
Comment:	Bradenhead plubed to surface.								
Corrective Action:					Date:				
Facility ID:	440246	Type:	WELL	API Number:	123-40757	Status:	DG	Insp. Status:	DG
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

**BradenHead**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection.</a>	carlilec	12/09/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674004696	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024862</a>