

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/09/2016
Submitted Date:
12/09/2016
Document Number:
674004696

FIELD INSPECTION FORM

Loc ID 330721 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440242	WELL	DG	10/26/2015	LO	123-40753	Moser H34-725	DG
440243	WELL	DG	11/20/2015	LO	123-40754	Moser H22-715	DG
440244	WELL	DG	11/12/2015	LO	123-40755	Moser H34-717	DG
440245	WELL	DG	11/03/2015	LO	123-40756	Moser H22-725	DG
440246	WELL	DG	11/27/2015	LO	123-40757	Moser H22-711	DG

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	440242	Type:	WELL	API Number:	123-40753	Status:	DG	Insp. Status:	DG	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
BradenHead										
Comment:	Bradenhead plubed to surface.									
Corrective Action:							Date:			
Facility ID:	440243	Type:	WELL	API Number:	123-40754	Status:	DG	Insp. Status:	DG	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
BradenHead										
Comment:	Bradenhead plubed to surface.									
Corrective Action:							Date:			
Facility ID:	440244	Type:	WELL	API Number:	123-40755	Status:	DG	Insp. Status:	DG	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
BradenHead										
Comment:	Bradenhead plubed to surface.									
Corrective Action:							Date:			
Facility ID:	440245	Type:	WELL	API Number:	123-40756	Status:	DG	Insp. Status:	DG	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
BradenHead										
Comment:	Bradenhead plubed to surface.									
Corrective Action:							Date:			
Facility ID:	440246	Type:	WELL	API Number:	123-40757	Status:	DG	Insp. Status:	DG	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			

BradenHead

Comment:

Corrective Action:

Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	12/09/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674004696	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4029044