

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2016

Submitted Date:

12/16/2016

Document Number:

666802825**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 323837 Murray, Richard 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210931	WELL	PR	10/28/2005	GW	045-06689	MAMM CREEK RANCH T45-20P (K20E)	PR

General Comment:[Inspection is to witness Plug and abandoned well](#)

Inspected Facilities									
Facility ID:	210931	Type:	WELL	API Number:	045-06689	Status:	PR	Insp. Status:	PR
Workover									
Comment:	Back out lock pins (3-3/4" out) Note: 7" PLS Halliburton Packer is said to be set @ 4265' w/ 20k lbs. of compression. P/U hanger out of bowl @ 8k lbs. Engage tongs and turn string to Right (2 turns) and continue picking up, Felt Packer released and saw signs of elements released because Csg went on a vacuum.								
Corrective Action:								Date:	