

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2016

Submitted Date:

12/13/2016

Document Number:

680301459**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 313725 SCHURE, KYM 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10203Name of Operator: BLACK RAVEN ENERGY INCAddress: 165 S UNION BLVD SUITE 410City: LAKEWOOD State: CO Zip: 80228**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------|---------|
| Wehrer, Gene | | gwehrer@enerjexresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 224976 | WELL | SI | 06/01/1998 | GW | 087-05369 | GLENN G-1 | SI |

General Comment:[Bradenhead Inspection](#)

Location**Lease Road:**

| | | | |
|-------------------|--------------|-------|--|
| Type | Access | | |
| comment: | Satisfactory | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Satisfactory

Corrective Action: _____ Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------|------------------------------------|-------|-----------------|
| Type: Other | # 0 | | corrective date |
| Comment: | No change in equipment inventoried | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 224976 | Type: | WELL | API Number: | 087-05369 | Status: | SI | Insp. Status: | SI |
| | | | | | | | | | |
| BradenHead | | | | | | | | | |
| | | | | | | | | | |
| Comment: Instantaneous PSIG = 0 . | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | In Process | Other | In Process | | | |

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 680301459 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025966 |