

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2016

Submitted Date:

12/13/2016

Document Number:

674901390**FIELD INSPECTION FORM**
 Loc ID 325653 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10434Name of Operator: ATOM PETROLEUM LLCAddress: 3323 N MIDLAND DR #113City: MIDLAND State: TX Zip: 79707**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Weems, Mark		mark.weems@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
St John, William (Cal)		cal.stjohn@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215172	WELL	TA	05/18/2016	GW	067-06777	TAYLOR 3	EI

General Comment:

On December 9, 2016 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Atom Petroleum Taylor #3. For the most recent field inspection report of this facility, please refer to document #674901324.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing signs near entrance to location and near pump jack. COGCC stickers are intact.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Chain installed by COGCC staff on 9/27/16, to the prime mover is still in place.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		37.138484,-108.130605
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Liner does not wrap up sides of containment berm. Corrective action date from inspection document #685200193.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.4.			Date: 07/22/2016

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Earthen berm constructed by COGCC staff around wellhead cellar is intact and appears to be functioning as intended.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On December 9, 2016 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Atom Petroleum Taylor #3. For the most recent field inspection report of this facility; please refer to document #674901324. The purpose of this site visit was to monitor the amount of fluids, if any, in the wellhead cellar. The cellar was approximately half way full of ice, upon inspection. The dirt berm surrounding the cellar is still intact. Vehicle tracks and foot prints were observed in the snow during this inspection.	hughesj	12/13/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901390	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031913
674901391	Storm water control berm around cellar.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4026052
674901392	Cellar is approximately half way full of ice.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4026053
674901393	Chain attached to prime mover is still intact.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4026054
674901394	Taylor #3 tank battery.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4026055