

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2016

Submitted Date:

12/20/2016

Document Number:

685301997**FIELD INSPECTION FORM**
 Loc ID 333707 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258267	WELL	PR	02/27/2002	GW	067-08347	LEMON J 2	PR
288243	WELL	PR		GW	067-09274	LEMON J 3	PR
288244	WELL	PR		GW	067-09273	LEMON J 4	PR

General Comment:

Inspection report contains corrective actions and comments. See Signs/Marker, Good Housekeeping and Stormwater Sections of report for additional details. See link at end of report for path to downloadable pictures.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	The sign for the Lemon J 4 API #067-09273 sign is peeling and needs to be replaced.			
Corrective Action:	Install sign to comply with Rule 210.b			Date: 02/19/2017
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	There are removed parts left at every wellhead. Screens, pipe, nipples and valves.			
Corrective Action:	Remove or install parts to comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date: 01/20/2017
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Post and Wire			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Panel			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Panel - Includes Produced Water Tank and Gas Meter Run			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Telemetry Equipment			

Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Wellhead				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 2				
Comment:	Double				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 8				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:	Electric Motor				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Electrical Service Equipment				
Corrective Action:				Date:	
Type: Flow Line	# 3				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 2				
Comment:	Linear Rod Pump				
Corrective Action:				Date:	
Type: Gas Meter Run	# 3				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 BBLS

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 258267 Type: WELL API Number: 067-08347 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 288243 Type: WELL API Number: 067-09274 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 288244 Type: WELL API Number: 067-09273 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Gravel	Pass	Self Inspection	Fail	
Waddles	Fail					
Check Dams	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Rip Rap	Fail					
Gravel	Fail					

Comment: The fill slope on the E side of location has numerous erosion channels. Erosion channels where rip rap was installed require additional BMP as the erosion channels have widened by cutting along side of rip rap. Installed waddles have failed and are no longer functioning as sediment has filled in the backside of waddle and is now allowing stormwater and sediment to over run waddles.

Corrective Action: Repair or install required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 01/20/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302009	Lemon J 4 Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033077
685302010	Piping propped on fencing with fittings piled at base	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033078
685302011	Linear Rod Pump Housing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033079
685302012	Full waddle and frozen flow	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033080
685302013	Erosion channel off edge of location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033081
685302014	Rip Rap with erosion channel beside it and additional Erosion Channel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033082
685302016	Erosion Channel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033083