

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/19/2016
Submitted Date:
12/20/2016
Document Number:
672500267

FIELD INSPECTION FORM

Loc ID 409322 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 93200
Name of Operator: VESSELS OIL & GAS COMPANY
Address: 8435 W 88TH AVE
City: ARVADA State: CO Zip: 80005

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251280	WELL	DA	03/31/1996	DA	123-19083	ERIE CHAMPLIN 18-9	DA

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 251280 Type: WELL API Number: 123-19083 Status: DA Insp. Status: DA

Complaint

Comment: [Complaint #: 200440782/200440777/200440779](#)
 Field Inspector Assigned: Jason E. Gomez
 Complaint Received:
 Date: 12-19-2016 Time 0730 Hrs
 Contacted by Inspector:
 Date: 12-19-2016 Time 1500 Hrs
 Well Number#: 05-123-19083 Location #: 409322
 Inspection Document #: 672500267
 Complainant: Peter Sarinana/Chelsea Incorvaia/Ashleigh Phone:
 Address:
 Nature of complaint: Noise/Lighting
 Field Inspector Actions:
 On 12-19-2016, I was contacted by Megan Adamczyk of the COGCC in reference to a complaints coming from the Erie Champlin location.
 The complaints indicated they were experiencing a loud grinding noise, and lighting issues coming from the Erie Champlin 18-9 location. The complainants indicated at night time the lights from location were shinning into his home.
 I performed a complete site inspection at locations. At the time of inspection, I observed an Ensign pulling unit performing a re-entry operation at the location under the direction of Crestone operations. During my inspection I observed approx. 4 light stands at location with all of the lights pointed toward the ground and toward the center of location. At the time of the inspection the lights were not in use.
 I also performed a sound study to the south of the location toward the complainant's home approx. 350' from the source of the sound on location. A second sound study was conducted to the east of the location toward the other complainant's residence. See inspection Doc #672500267 for the results of attached sound study.
 At the time of inspection, no violations of COGCC rules were observed.

Corrective Action: _____ Date: _____

Workover

Comment: [DRILL OUT RE-ENTRY FOR P&A](#)

Corrective Action: _____ Date: _____