

Construction and Stormwater Inspection



Photo 1. Photo taken from the entrance of location, facing East. Location IN-PROCESS of being built. Topsoil was not salvaged before construction of location. Also, no stormwater or erosion control BMPs in place prior to or during construction.

Construction and Stormwater Inspection



Photo 2. Photo taken from the eastern location, facing West. Location IN-PROCESS of being built. Topsoil was not salvaged before construction of location. Also, no stormwater or erosion control BMPs in place prior to or during construction.