

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2016

Submitted Date:

12/16/2016

Document Number:

666802825**FIELD INSPECTION FORM**

Loc ID 323837 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210931	WELL	PR	10/28/2005	GW	045-06689	MAMM CREEK RANCH T45-20P (K20E)	PR

**General Comment:**[Inspection is to witness Plug and abandoned well](#)

**Inspected Facilities**Facility ID: 210931 Type: WELL API Number: 045-06689 Status: PR Insp. Status: PR**Workover**

Comment: Back out lock pins (3-3/4" out) Note: 7" PLS Halliburton Packer is said to be set @ 4265' w/ 20k lbs. of compression. P/U hanger out of bowl @ 8k lbs. Engage tongs and turn string to Right (2 turns) and continue picking up, Felt Packer released and saw signs of elements released because Csg went on a vacuum.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802825	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4036116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4036116</a>