

Inspector Name:

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109**FIELD INSPECTION FORM**

|                   |  |   |  |
|-------------------|--|---|--|
| Loc ID _____      | Inspector Name: _____<br>LUJAN, CARLOS | On-Site Inspection <input type="checkbox"/> | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>8 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested |
| 2A Doc Num: _____ |  |   |  |

|  |  |  |  |
|--|--|--|--|
| <b>Operator Information:</b><br>OGCC Operator Number: 10442<br>Name of Operator: HUNTER RIDGE ENERGY SERVICES LLC<br>Address: 370 17TH STREET #1700<br>City: DENVER State: CO Zip: 80202 |  |  |  |
|--|--|--|--|

**Contact Information:**

| Contact Name     | Phone | Email                      | Comment                      |
|------------------|-------|----------------------------|------------------------------|
| Middleton, Brett |       | Brett.Middleton@encana.com | Environmental Specialist     |
| Rider, Lindsey   |       | Lindsey.Rider@encana.com   | Manager, Field Environmental |
| Lujan, Carlos    |       | carlos.lujan@state.co.us   | EPS, NW Region               |
| Fischer, Alex    |       | alex.fischer@state.co.us   | Environmental Supervisor, NW |
| Kasten, Matt     |       | Matthew.Kasten@encana.com  | Environmental                |
| Spencer, Stan    |       | stan.spencer@state.co.us   | EPS, NW Region               |

**General Comment:**

Environmental inspection conducted as a follow-up to Site Assessment and Remediation in the valley north and downgradient of the A27 pipeline spill/release (Spill/Release Point ID #446199, REM #9748). Cool and sunny. On Site with Brett Middleton from Encana/Hunter Ridge (HR) and geologist Wesley Toews from LTE, Rifle office.

The drilling operation was conducted to complete the Phase III Environmental Assessment, document submitted to the COGCC on 10/06/2016 (doc #401125566). A roto sonic drilling rig was used to improve core sampling recovery and well construction. Poorly cemented sandstone was encountered mostly on monitoring wells on both sides (east and west) of the valley. Clayey soil was encountered on monitoring wells in the valley, on the east side of the creek. Today, Oct 20, 2016, the subcontractor is completing MW-18 (See attached photos). Water level at about 53' bgs. No free product observed at this point.

Note: During the process of pouring sand, it was noticed that sand got lost at about 40 feet bgs (more sand had to be poured than expected). Driller indicated that the well had not caved in.

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| The COGCC will continue to inspect the Site as Site Assessment and Remediation activities progress. Encana will continue to submit periodic updates. | lujanc | 12/19/2016 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 671000495    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031538</a> |
| 671000496    | Completing MW-18     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031504">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031504</a> |
| 671000497    | Pouring sand         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031505</a> |



Inspection Date:

10/20/2016

Submitted Date:

12/19/2016

Document Number:

671000495

|           |                                 |   |
|-----------|---------------------------------|---|
| 671000498 | Measuring water level           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031506</a> |
| 671000499 | Finishing installation of MW-18 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031507">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031507</a> |