

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2016

Submitted Date:

12/14/2016

Document Number:

672500258

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
409322 \_\_\_\_\_ Gomez, Jason \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 93200  
 Name of Operator: VESSELS OIL & GAS COMPANY  
 Address: 8435 W 88TH AVE  
 City: ARVADA State: CO Zip: 80005

**Findings:**

- 3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name    | Phone | Email                            | Comment |
|-----------------|-------|----------------------------------|---------|
| Adamczyk, Megan |       | megan.adamczyk@state.co.us       |         |
| ,               |       | Cogcc.inspections@crestonepr.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 251280      | WELL | DA     | 03/31/1996  | DA         | 123-19083 | ERIE CHAMPLIN 18-9 | DA          |

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |   |       |
|--------------------|---|-------|
| Type               | Field Flare                               |       |
| Comment:           | ENCLOSED NOT IN USE AT TIME OF INSPECTION |       |
| Corrective Action: |   | Date: |

**Inspected Facilities**

Facility ID: 251280 Type: WELL API Number: 123-19083 Status: DA Insp. Status: DA

**Complaint**

Comment: **Complaint #: 200440714**  
**Field Inspector Assigned: Jason E. Gomez**  
**Complaint Received:**  
**Date: 12-13-2016 Time 2100 Hrs**  
**Contacted by Inspector:**  
**Date: Time12-14-2016 1430 Hrs**  
**Well Number#: 05-123-19083 Location #: 409322**  
**Inspection Document #: 672500258**  
**Complainant: Darren Champion Phone: 303-482-1734**  
**Address: 484 Main St Erie Co 80516**  
  
**Nature of complaint: Lighting**  
  
**Field Inspector Actions:**  
 On 12-14-2016, I was contacted by Dave Kulman Deputy Director of the COGCC in reference to a complaint at the residence of the complainant Darren Champion at 428 Main St in Erie Colorado.  
  
 The complaint indicated in his complaint he was experiencing bright lights coming from the Erie Champlin 18-9 location. Upon speaking with him he said the lights were bothering him on his drive home in the evenings.  
  
 I performed a complete site inspection at locations. At the time of inspection all light appeared to be pointed toward the ground and toward the center of the location per COGCC rules. At the time of the inspection the lights were not in use. See inspection Doc #672500258 for attached photos of lighting at location.  
  
 At the time of inspection, I no violations of COGCC rules were observed.

Corrective Action:

Date:

**Workover**

Comment: **RE-ENTRY DRILL OUT ALL LIGHT WERE POINTED DOWN TOWRD THE GROUND AND CENTER OF LOCATION AT TIME OF INSPECTION SEE ATTACHED PHOTO**

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                       | URL   |
|--------------|-----------------------------------|---|
| 672500258    | INSPECTION SUBMITTED              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031288">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031288</a> |
| 672500259    | LIGHTS APPEAR TO BE IN COMPLIANCE | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031231">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031231</a> |