

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2016

Submitted Date:

12/20/2016

Document Number:

672500267**FIELD INSPECTION FORM**
 Loc ID 409322 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 93200Name of Operator: VESSELS OIL & GAS COMPANYAddress: 8435 W 88TH AVECity: ARVADA State: CO Zip: 80005**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251280	WELL	DA	03/31/1996	DA	123-19083	ERIE CHAMPLIN 18-9	DA

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 251280 Type: WELL API Number: 123-19083 Status: DA Insp. Status: DA

**Complaint**

Comment: [Complaint #: 200440782/200440777/200440779](#)

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 12-19-2016 Time 0730 Hrs

Contacted by Inspector:

Date: 12-19-2016 Time 1500 Hrs

Well Number#: 05-123-19083 Location #: 409322

Inspection Document #: 672500267

Complainant: Peter Sarinana/Chelsea Incorvaia/Ashleigh Phone:

Address:

Nature of complaint: Noise/Lighting

Field Inspector Actions:  
On 12-19-2016, I was contacted by Megan Adamczyk of the COGCC in reference to a complaints coming from the Erie Champlin location.

The complaints indicated they were experiencing a loud grinding noise, and lighting issues coming from the Erie Champlin 18-9 location. The complainants indicated at night time the lights from location were shining into his home.

I performed a complete site inspection at locations. At the time of inspection, I observed an Ensign pulling unit performing a re-entry operation at the location under the direction of Crestone operations. During my inspection I observed approx. 4 light stands at location with all of the lights pointed toward the ground and toward the center of location. At the time of the inspection the lights were not in use.

I also performed a sound study to the south of the location toward the complainant's home approx. 350' from the source of the sound on location. A second sound study was conducted to the east of the location toward the other complainant's residence. See inspection Doc #672500267 for the results of attached sound study.

At the time of inspection, no violations of COGCC rules were observed.

Corrective Action:

Date:

**Workover**Comment: [DRILL OUT RE-ENTRY FOR P&A](#)

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500267	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034037</a>