

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/22/2016

Submitted Date:

12/22/2016

Document Number:

674703487**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 324222      LONGWORTH, MIKE      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE      State: CO      Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 265919      | WELL | PR     | 01/10/2003  | GW         | 045-09089 | PA 334-27     | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |   |       |                 |
|--------------------|---|-------|-----------------|
| Type: Plunger Lift | # |       | corrective date |
| Comment:           |   |       |                 |
| Corrective Action: |   | Date: |                 |

**Tanks and Berms:**

| Contents           | #               | Capacity | Type | Tank ID | SE GPS |
|--------------------|-----------------|----------|------|---------|--------|
|                    |                 |          |      |         |        |
| Comment:           | Remote facility |          |      |         |        |
| Corrective Action: |                 |          |      |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |



| Inspected Facilities |                |       |      |             |           |         |    |               |    |
|----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 265919         | Type: | WELL | API Number: | 045-09089 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                |       |      |             |           |         |    |               |    |
| Comment:             | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:   |                |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
| Seeding          | Pass            |                         |                       |  |                          |         |
| Compaction       | Pass            |                         |                       |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
| Gravel           | Pass            |                         |                       |  |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 674703487    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4035991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4035991</a> |