



Photo#1: There is no evidence of the AL or DA Well on this Active Location.

December 27, 2016

Inspection Photos: Encana AL & DA Shaeffer API#045-10455 & 045-10452



Photo#2: There is no evidence of the AL or DA Well on this Active Layered Location.

December 27, 2016

Inspection Photos: Encana AL & DA Shaeffer API#045-10455 & 045-10452