



Photo 1. View of the southern edge of the project area from the southeastern corner facing westward. A new diversion berm has been installed and appears to be functioning.



Photo 2. View of the project area from the southeastern corner of the project area facing center.





Photo 3. View of area where stormwater drains off of the southeastern corner of the project area that does not appear to be eroding significantly. This should continue to be monitored and BMPs applied if erosion worsens.