

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2017

Submitted Date:

01/06/2017

Document Number:

666802869**FIELD INSPECTION FORM**

Loc ID 334592 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211097	WELL	PR	09/04/2013	GW	045-06856	PARKER RANCH 14-10	PA
257129	WELL	PR	06/01/2002	GW	045-07515	ROSE RANCH 14-11(J14)	TA
257130	WELL	PR	09/10/2013	GW	045-07516	ROSE RANCH 14-9 (J14)	TA
257131	WELL	PA	04/14/2015	GW	045-07517	ROSE RANCH 14-7 (J14)	PA
257132	WELL	PR	01/30/2001	GW	045-07518	ROSE RANCH 14-6 (J14)	TA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents	#	Capacity	Type			Tank ID	SE GPS		
CONDENSATE	2	300 BBLS	STEEL AST				39.444062,-107.741516		
Comment:									
Corrective Action:								Date:	

**Paint**

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valve open		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 211097 Type: WELL API Number: 045-06856 Status: PR Insp. Status: PAFacility ID: 257129 Type: WELL API Number: 045-07515 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: No current form 4 on file to continue Temporarily Abandoned well statusCorrective Action: Contact COGCC engineering staff Date: \_\_\_\_\_Facility ID: 257130 Type: WELL API Number: 045-07516 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: No current form 4 on file to continue Temporarily Abandoned well statusCorrective Action: Contact COGCC engineering staff Date: 01/13/2017Facility ID: 257131 Type: WELL API Number: 045-07517 Status: PA Insp. Status: PAFacility ID: 257132 Type: WELL API Number: 045-07518 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: No current form 4 on file to continue Temporarily Abandoned well statusCorrective Action: Contact COGCC engineering staff Date: 01/13/2017

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT