

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/20/2016
Submitted Date:
01/05/2017
Document Number:
677900215

FIELD INSPECTION FORM

Loc ID 324639 Inspector Name: FISCHER, ALEX On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 16000 DALLAS PARKWAY #875
City: DALLAS State: TX Zip: 75248-

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Grant,		regulatory@foundationenergy.com	
Carter Peace		cpeace@tasman-geo.com	
Caitlin O'Hair		cohair@foundationenergy.com	
Joel Sauer		jsauer@foundationenergy.com	
Waldron, Emily		emily.waldron@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Regulatory, Foundation		regulatory@foundationenergy.com	Regulatory Email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324639	LOCATION	AC			-	ALLARD-610N79W 30SENE	EI
441949	SPILL OR RELEASE	CL	05/26/2015		-	SPILL/RELEASE POINT	EI
441950	SPILL OR RELEASE	AC	05/20/2016		-	SPILL/RELEASE POINT	EI

General Comment:

On December 20, 2016 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Foundation Energy Management LLC (Foundation) Facility ID: 324639. Weather was sunny to partially cloudy and temperature app 25s degree F and wind from the south, snow was present on the ground. Well was not producing at time of inspection. For the most recent Environmental Field inspection report of this facility, please refer to document # 677900194. The overall inspection status shall remain the same as that document until all corrective actions have been completed.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted or information inaccurate.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/06/2017

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 324639 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 324639 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 441949 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 441950 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Comment	User	Date
<p>On December 20, 2016 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Foundation Energy Management LLC (Foundation) Facility ID: 324639. Weather was sunny to partially cloudy and temperature app 25s degree F and wind from the south, snow was present on the ground. Well was not producing at time of inspection. For the most recent Environmental Field inspection report of this facility, please refer to document # 677900194. The overall inspection status shall remain the same as that document until all corrective actions have been completed.</p> <p>The following is a summary: Five (5) one-inch monitoring wells installed around the separator building. Footprints were noted around each monitoring and staining on the surface of the snow was observed near the western most monitoring well. Tanks are labeled and placard but missing the Emergency Contact information. Ditches/canals were not flowing at time of the Inspection. Corrective Actions: By January 31, 2017, provide documentation that the previous corrective action identified in Inspection 677900194. Repair (animal burrows) or install berms or other secondary containment devices per Rule 906.d.(1). By February 3, 2017 comply with Rule 210.d. Provide status update via Supplemental eForm 27 regarding the referenced Spill/Release. Refer to Document Number 2526739 for information required. Use remediation number REM 9686 on all correspondence.</p>	fischera	01/04/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677900217	INSP Summary 20161220 Allard Inspection Facility ID 324639 Photo log.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044330
677900218	20161220Foundation Inspection Facility ID 324639.docx	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044331