

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2017

Submitted Date:

01/06/2017

Document Number:

666802865**FIELD INSPECTION FORM**

Loc ID 334563 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

- 6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211184	WELL	TA	10/24/2014	GW	045-06943	PARKER RANCH 10-9	TA
259382	WELL	PR	10/17/2001	GW	045-07720	ROSE RANCH 10-16 (I10)	PR
259383	WELL	PR	08/30/2001	GW	045-07721	ANDREW 10-15 (I10)	PR
259384	WELL	PR	04/15/2002	GW	045-07722	ROSE RANCH 10-10 (I10)	PR
259385	WELL	PR	04/08/2002	GW	045-07723	ROSE RANCH 10-9A (I10)	SI

General Comment:

Inspected Facilities				
Facility ID: <u>211184</u>	Type: <u>WELL</u>	API Number: <u>045-06943</u>	Status: <u>TA</u>	Insp. Status: <u>TA</u>
Idle Well				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: No current form 4 on file to continue Temporarily Abandoned well status				
Corrective Action: Contact COGCC engineering staff				Date: <u>01/13/2017</u>
Facility ID: <u>259382</u>	Type: <u>WELL</u>	API Number: <u>045-07720</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: <u>259383</u>	Type: <u>WELL</u>	API Number: <u>045-07721</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: <u>259384</u>	Type: <u>WELL</u>	API Number: <u>045-07722</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: <u>259385</u>	Type: <u>WELL</u>	API Number: <u>045-07723</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last posted production numbers OCT 2016				
Corrective Action:				Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401179597	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046175