



**photo 1:** Facing northeast toward the beginning of the access road.



**photo 2:** Facing northwest along the access road.





**photo 3:** Facing northeast along the access road.



**photo 4:** Facing east along the access road.





**photo 5:** Facing east along the access road. This are signs of vehicle rutting in this area.



**photo 6:** End of the access road where the ranch road turns to the northeast,