



Photo#1: Overview of Location to North from Interim Reclamation Area.

January 12, 2017

Inspection Photos: Encana Loc#335200 N Parachute



Photo#2: Well Vegetated Fill Slope at west side of Location Entry.

January 12, 2017

Inspection Photos: Encana Loc#335200 N Parachute





Photo#3: SW Cutting across Access Road from NE.

Inspection Photos: Encana Loc#335200 N Parachute

January 12, 2017



Photo#4: Water flow to SW

Inspection Photos: Encana Loc#335200 N Parachute

January 12, 2017





Photo#5: Water discharging into Drainage.

Inspection Photos: Encana Loc#335200 N Parachute

January 12, 2017