



photo 1: Facing west along the access road. The road is not contoured and regraded.



photo 2: The soils along the access road are compacted and vegetation has not established.



photo 3: Facing west toward the location.



photo 4: Vegetation has not adequately established at the location and the soils seem to be compacted.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: Facing south toward the surrounding undisturbed pasture (reference area).