

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2017

Submitted Date:

01/13/2017

Document Number:

674901441**FIELD INSPECTION FORM**

Loc ID 306898 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Tahmahkera, Kerry	(970) 563-4000	maralextech@gmail.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275103	WELL	PR	08/12/2014	GW	067-08998	CORY JACK 33-7-11 2	EI

General Comment:

On January 5, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Cory Jack 33-7-11 #2. For the most recent field inspection report of this facility, please refer to document #680600644.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign mounted to pump jack.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Label and placard on chemical injection container and lube oil container.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Partial sound wall on south side of pump jack.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
<p>Comment: Secondary containment for lube oil container and chemical injection system container. The expanded metal wildlife screen in the secondary containment for the chemical injection system is submerged in fluids.</p> <p>Corrective Action: <input type="text"/></p> <p>Date: <input type="text"/></p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments

Comment	User	Date
On January 5, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Cory Jack 33-7-11 #2. For the most recent field inspection report of this facility, please refer to document #680600644. During this inspection it was observed that the expanded metal wildlife screen in the secondary containment for the chemical injection system is submerged in fluids.	hughesj	01/13/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401184858	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051540
674901442	Cory Jack 33-7-11 #2 pump jack and well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051525
674901443	Partial sound wall and location BMP.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051526
674901444	Expanded metal wildlife screen is submerged.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051527