

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2017

Submitted Date:

01/27/2017

Document Number:

666802909**FIELD INSPECTION FORM**

Loc ID 334561 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257180	WELL	PR	06/01/2002	GW	045-07529	SCHAEFFER 11-8 (I11W)	PR
257181	WELL	PR	01/30/2001	GW	045-07530	SCHAEFFER 11-16 (I11W)	PR
257183	WELL	PR	01/30/2001	GW	045-07532	SCHAEFFER 11-9 (I11W)	PR
257184	WELL	PR	06/01/2002	GW	045-07533	SCHAEFFER 12-12 (I11W)	PR
281186	WELL	PR	04/18/2007	GW	045-11405	SHAEFFER 12-12B (I11W)	PR
281187	WELL	PR	04/21/2007	GW	045-11406	SHAEFFER 11-9C (I11W)	PR

General Comment:

Facilities shared with location ID 334589

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

3

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

4

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Vertical Heated Separator

5

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		39.459291,-107.736913

Comment: Corrective Action: Date: **Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Inspected Facilities									
Facility ID:	257180	Type:	WELL	API Number:	045-07529	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	257181	Type:	WELL	API Number:	045-07530	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	257183	Type:	WELL	API Number:	045-07532	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	257184	Type:	WELL	API Number:	045-07533	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	281186	Type:	WELL	API Number:	045-11405	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281187	Type:	WELL	API Number:	045-11406	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Ditches	Pass			
Berms	Pass					

Comment:

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT