

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2017

Submitted Date:

01/23/2017

Document Number:

674603109**FIELD INSPECTION FORM**
 Loc ID 333044 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hazard, Ellice		ellice.hazard@state.co.us	
Allison, Rick		rick.allison@state.co.us	
,		cogccinspection@pdce.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290755	WELL	PR	01/31/2009	OW	123-25215	HANKINS 44-17U	EG

**General Comment:**

COGCC Engineering Integrity Inspection performed on January 18th, 2017 in response to initial form 19 spill report Doc #401184573 received on 1/13/2017 that outlines: A reportable release was found within secondary containment on the Hankins 34, 44-17U due to a leaking oil tank. Once discovered, the flowline was shut and tank bottomed out. Current recovery efforts are mitigating impacts. The details of observations made during this field inspection are available in the tanks/ berms and flowline sections of this report. No PDC Energy or contract personnel were on site at the time of this field inspection. Photo's have been uploaded and can be accessed via link(s) at the end of this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:	Tank repair work is in progress; The manway opening/ cover has a new gasket, bolts and the dump line has been repaired; The area inside the berm and around the tank has been worked/ graded and a backhoe is on location. Note: Maintain records of tank repairs and/ or replacements completed. Ensure integrity of crude oil and produced water tanks prior to returning to service in order to prevent future releases.					
Corrective Action:					Date:	

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	

**Flaring:**

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date:

**Inspected Facilities**Facility ID: 290755 Type: WELL API Number: 123-25215 Status: PR Insp. Status: EG**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: Age: Contents: Crude Oil

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Repair/ replacement work has been completed on the crude oil dump line. The dump line entering the oil tank (bottom) has new ball valves and pipe fittings. Note: Maintain records of flowline repairs/ replacements completed. Conduct flowline pressure testing (confirm integrity of flowline repairs/ replacements completed and retain testing data/ chart) prior to returning flowlines to service.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401190944	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056692">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056692</a>
674603117	Battery and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056689</a>
674603119	Dump line tie in at crude oil tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056690">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056690</a>
674603120	Location/ work in progress	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056691">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056691</a>