

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/27/2017
Submitted Date:
01/30/2017
Document Number:
678300648

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|-------------------------------|---------------------------------|
| Avant, Paul | 720-929-6457 | Paul.Avant@Anadarko.com | |
| | | luke.reddy@anadarko.com | |
| | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|---------------------|-------------|
| 449004 | SPILL OR RELEASE | AC | 01/23/2017 | | - | SPILL/RELEASE POINT | EI |

General Comment:

related inspection of well pad area on same day filed as 685501846 (by John Montoya). Photos of well pad and equipment on site included in that inspection.
This inspection is of the area to the north of the well pad that was impacted by spray of liquids before well control was established. Much equipment remained on location and was being cleaned with hydrovac trucks. Representative of operator on site indicated cleanup of soils in well location would begin after cleanup of equipment and relocation of equipment.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Spill 449004 outline of areas thought to be is in documents25227595 as provided on 24January2017 by operator.
 This inspection consisted of a track around the eastern and northern perimeter of the release area of areas to the north of the access road off CR 41 and starting just north of the well location.
 The access road area had been partially scraped of hydrocarbons as shown in attached photo looking east and west from point to N of Adamson location
 An area to the west of the noise baffle on west side of location was being scraped with impacted soils being removed from site under manifest for disposal.

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 449004 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 678300649 | looking east on access road to battery | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063660 |
| 678300650 | looking west on access road to battery | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063661 |
| 678300651 | pad from access road to N | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063662 |