



**Inspected Facilities**

Facility ID: 295296 Type: WELL API Number: 057-06465 Status: PR Insp. Status: PR

**Workover**

Comment: Workover on location replacing drip pot.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401195193	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4060994">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4060994</a>