

Interim Reclamation and Stormwater Inspection

01/26/2017

Operator: Bonanza Creek

Location ID: 427275

Weld County, CO

NENW Section 35 T7N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Interim Reclamation and Stormwater Inspection



Photo 1. Photo taken from the northern interim area, facing West. Germination apparent throughout most of the interim area.

Interim Reclamation and Stormwater Inspection



Photo 2. Photo taken from the northwest production area, facing West. Germination apparent throughout most of the interim area.

Interim Reclamation and Stormwater Inspection



Photo 3. Photo taken from the northwest production area, facing South. Germination apparent throughout most of the interim area.

Interim Reclamation and Stormwater Inspection



Photo 4. Photo taken from the southern production area, facing East. Germination apparent throughout most of the interim area. Germination lacks along portions of this interim area. May need additional reclamation activities to be performed to achieve Rule 1003 standards.

Interim Reclamation and Stormwater Inspection



Photo 5. Photo taken from the southeast production area, facing East. Germination apparent throughout most of the interim area.

Interim Reclamation and Stormwater Inspection



Photo 6. Photo taken from the northeast location, facing South. Germination apparent throughout most of the interim area. Germination lacks along portions of this interim area. May need additional reclamation activities to be performed to achieve Rule 1003 standards.

Interim Reclamation and Stormwater Inspection



Photo 7. Photo taken from the southern location, facing East, towards the flare. Kochia weeds next to the flare pose a fire hazard.