

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2017

Submitted Date:

01/30/2017

Document Number:

678300648**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐  
 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		luke.reddy@anadarko.com	
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>
Avant, Paul	720-929-6457	Paul.Avant@Anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449004	SPILL OR RELEASE	AC	01/23/2017		-	SPILL/RELEASE POINT	EI

**General Comment:**

related inspection of well pad area on same day filed as 685501846 (by John Montoya). Photos of well pad and equipment on site included in that inspection.

This inspection is of the area to the north of the well pad that was impacted by spray of liquids before well control was established. Much equipment remained on location and was being cleaned with hydrovac trucks. Representative of operator on site indicated cleanup of soils in well location would begin after cleanup of equipment and relocation of equipment.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Spill 449004 outline of areas thought to be is in documents 25227595 as provided on 24 January 2017 by operator.

This inspection consisted of a track around the eastern and northern perimeter of the release area of areas to the north of the access road off CR 41 and starting just north of the well location.

The access road area had been partially scraped of hydrocarbons as shown in attached photo looking east and west from point to N of Adamson location

An area to the west of the noise baffle on west side of location was being scraped with impacted soils being removed from site under manifest for disposal.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 449004 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401197590	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063663">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063663</a>
678300649	looking east on access road to battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063660">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063660</a>
678300650	looking west on access road to battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063661">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063661</a>
678300651	pad from access road to N	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063662">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063662</a>