

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2017

Submitted Date:

01/30/2017

Document Number:

682401741**FIELD INSPECTION FORM**Loc ID: 448779 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Operator Information:**OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION\* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC_FIR@billbarrettcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448775	WELL	XX	12/18/2016		123-44014	WILL TRUST 6-62-10-4846BN2	CI
448776	WELL	XX	12/18/2016		123-44015	WILL TRUST 6-62-10-6462BN2	CI
448777	WELL	XX	12/18/2016		123-44016	WILL TRUST 6-62-10-4846BS2	CI
448778	WELL	XX	12/18/2016		123-44017	Will Trust 6-62-10-4951B2	CI

**General Comment:**

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401186568. It should be noted the Operator was installing a BMP (ditch and berm) along the southeast portion of the location while COGCC staff was inspecting the location. Operator must install sufficient stormwater BMPs prior to, or at the beginning of, construction.

**Location Construction**Location ID: 448779 CDP: \_\_\_\_\_

Comment: Topsoil has been salvaged, stored, and temporarily stabilized (i.e., tracked) along the eastern perimeter location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

DITCHES	Yes	
Comments: Erosion BMPs: <b>Ditch along the southeast location has not been built to a sufficient depth.</b> Other BMPs: 		
Corrective Action: <b>Install ditch to a sufficient depth along the described area.</b>		Date: 02/06/2017

BERMS	Yes	
Comments: Erosion BMPs: <b>Berm has not been built to a sufficient height and has not been compacted along the perimeter of location.</b> Other BMPs: 		
Corrective Action: <b>Install a sufficient berm and compact berm to manage pollutant contributions to stormwater runoff from unconsolidated soil material. Typical recommended minimum height of a berm is 15 inches at a 3:1 slope.</b>		Date: 02/06/2017

**Comment:** **BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.**

**Corrective Action:**   
 **Date:**

### On Site Inspection (305):

#### Surface Owner Contact Information:

Name:   
 Address:   
 Phone Number:   
 Cell Phone:

#### Operator Rep. Contact Information:

Landman Name:   
 Phone Number:   
 Date Onsite Request Received:   
 Date of Rule 306 Consultation:   
 Request LGD Attendance:

#### LGD Contact Information:

Name:   
 Phone Number:   
 Agreed to Attend:

#### Summary of Landowner Issues:

#### Summary of Operator Response to Landowner Issues:

#### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: <u>448775</u>	Type: <u>WELL</u>	API Number: <u>123-44014</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448776</u>	Type: <u>WELL</u>	API Number: <u>123-44015</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448777</u>	Type: <u>WELL</u>	API Number: <u>123-44016</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448778</u>	Type: <u>WELL</u>	API Number: <u>123-44017</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401742.</a>	binschusc	01/30/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401197514	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063632</a>
682401742	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063631</a>