

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/01/2017
Submitted Date:
02/01/2017
Document Number:
667600097

FIELD INSPECTION FORM

Loc ID 320283 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:
18 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Brandy	303-339-8600	bsmith@hrmresoures.net	303-893-6621
Pape, Terry	970-768-5700	tpape@hrmres.com	All Inspections
Prohaska, April	(303) 996-8697	aprohaska@hrmres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203350	WELL	PR	03/31/2008	GW	001-08859	AMOCO 44-17	PR

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Two track through farm ground.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign at wellhead identifies well as Amoco #24-17. Well is actually #44-17. The sign at the #24-17 identifies as the #44-17. Sign need swapped.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 03/01/2017
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Adequate.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Uncontrolled weeds and vegetation within 25' of wellhead. See attached photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 03/01/2017
Type	DEBRIS		
Comment:	Weeds and debris on south edge of tank battery, piles of rubble on north edge of lease reoad at well head, and roll of wire fencing on west side of battery. See attached photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 03/01/2017
Type	UNUSED EQUIPMENT		
Comment:	Farm equipment stored next to well head. See attached photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 05/01/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		

Comment:	Rod fence around wellhead.	Date:	
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Four wire barbed wire around battery.	Date:	
Corrective Action:		Date:	

Equipment:		corrective date
Type: Emission Control Device	# 1	
Comment:	Pilot light not light.	
Corrective Action:	Light pilot light.	Date: <u>02/03/2017</u>
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:	Two anchors at battery fence.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:	Avian protection measures installed on separator exhaust and ECD.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Tank is not painted adequately. See attached photo.				
Corrective Action:	Paint tanks per Rule 804.				Date: <u>07/01/2017</u>

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		
Comment:		70 BBL			
Corrective Action:					Date:
Paint					
Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 203350 Type: WELL API Number: 001-08859 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401199874	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4065557
667600118	Amoco 44-17 Inspection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4065542