

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2017

Submitted Date:

02/02/2017

Document Number:

666802929

FIELD INSPECTION FORM

Loc ID 336023 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 1050 17TH STREET #1700
 City: DENVER State: CO Zip: 80265

Findings:

- 4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------------------------|
| Knudson, Dwayne | 970-456-3335 | dknudson@ursaresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 284991 | WELL | PR | 02/10/2010 | GW | 045-12337 | HANGS A2 | PR |
| 284993 | WELL | PR | 02/10/2010 | GW | 045-12339 | HANGS A4 | PR |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | Comment | Corrective Action | Date | corrective date |
|-----------------------------------|-----|---------|-------------------|------|-----------------|
| Type: Plunger Lift | # 2 | | | | |
| | | | | | |
| Type: Ancillary equipment | # 0 | | | | |
| | | | | | |
| Type: Horizontal Heated Separator | # 2 | | | | |
| | | | | | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLS | STEEL AST | | |
| | | | | | |
| | | | | | |
| | | | | | |

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Comment:

Corrective Action:

Date:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 2 | 300 BBLS | STEEL AST | | 39.522618,-107.664375 |
| | | | | | |
| | | | | | |

Comment:

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 284991 Type: WELL API Number: 045-12337 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 284993 Type: WELL API Number: 045-12339 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |
| Seeding | In Process | | | | | |
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |
| Berms | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401200511 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066075 |