

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2017

Submitted Date:

02/03/2017

Document Number:

666802931**FIELD INSPECTION FORM**

Loc ID 334563 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211184	WELL	TA	10/24/2014	GW	045-06943	PARKER RANCH 10-9	TA
259382	WELL	PR	10/17/2001	GW	045-07720	ROSE RANCH 10-16 (I10)	PR
259383	WELL	PR	08/30/2001	GW	045-07721	ANDREW 10-15 (I10)	PR
259384	WELL	PR	04/15/2002	GW	045-07722	ROSE RANCH 10-10 (I10)	PR
259385	WELL	PR	04/08/2002	GW	045-07723	ROSE RANCH 10-9A (I10)	SI

General Comment:

Action required items noted in previous inspection have been satisfied

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

5

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

5

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment: Centralized battery						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

Paint

Condition Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS		
CONDENSATE		2	300 BBLS	STEEL AST			39.456250,-107.755620		
Comment:									

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 211184 Type: WELL API Number: 045-06943 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Form 4 on file to continue Temporarily Abandoned well status

Corrective Action: _____ Date: _____

Facility ID: 259382 Type: WELL API Number: 045-07720 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____ Date: _____

Facility ID: 259383 Type: WELL API Number: 045-07721 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____ Date: _____

Facility ID: 259384 Type: WELL API Number: 045-07722 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____ Date: _____

Facility ID: 259385 Type: WELL API Number: 045-07723 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last posted production numbers OCT 2016

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401201433	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066974